

03560.003330

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Van T. Pham
HIROTAKE ANDO)	
	:	Art Unit: 2627
Appln. No.: 10/608,108)	
	:	Conf. No.: 1047
Filed: June 30, 2003)	
	:	
For: OPTICAL INFORMATION)	
REPRODUCING APPARATUS	:	
HAVING A SERVO CONTROL)	
CIRCUIT	:	
)	
U.S. Patent No.: 7,304,919 B2	:	
)	
Issued: December 4, 2007	:	August 18, 2008

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form is attached.

The amount of \$100.00 to cover the statutory fee for such Certificate of Correction is being paid concurrently; please charge any deficiency in this fee, and credit any overpayment, to Deposit Account 06-1205.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/John A. Krause/
John A. Krause
Attorney for Patentees
Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

2355700v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,304,919 B2

DATED : December 4, 2007

INVENTOR(S) : HIROTAKE ANDO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 31, "a" should read --as--;
Line 41, "planer" should read --is planar--;
Line 50, "planer" should read --planar--;
Line 52, "planer" should read --planar--; and
Line 54, "planer" should read --planar--.

COLUMN 7

Line 14, "he" should read --the--; and
Line 54, "a" should read -- α --.

COLUMN 8

Line 5, "planer" should read --planar--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,304,919 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,304,919 B2

DATED : December 4, 2007

INVENTOR(S) : HIROTAKE ANDO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 4, "weight a" should read --weight α --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,304,919 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

2355700v1

